

Sample requirements

The certificate requirements for samples are set out in the following table (noting the split of samples per device type requiring UIT and GFI certificates):

Device Type	Number of Samples (per device submission)	Preloaded ZigBee Certificates (per sample)	Preloaded Organisation Certificates (per sample)
ESME	8	Production Certificates	UIT Root
			UIT Recovery
			UIT Supplier (ACB DS)
			UIT Supplier (ACB KA)
			UIT Supplier (ACB KA)
			UIT Network Operator (ACB DS)
			UIT Network Operator (ACB KA)
			UIT Access Control Broker (KA)
	UIT Transitional CoS (DS)		
	2	Test Certificates	GFI Root
			GFI Recovery
			GFI Supplier (Supplier DS)
			GFI Supplier (Supplier KA)
			GFI Supplier (Supplier KA Prepayment Top Up)
GFI Network Operator (DS)			
GFI Network Operator (KA)			
GFI Access Control Broker (KA)			
GFI Transitional CoS (DS)			

Device Type	Number of Samples (per device submission)	Preloaded ZigBee Certificates (per sample)	Preloaded Organisation Certificates (per sample)
GSME	8	Production Certificates	UIT Root
			UIT Recovery
			UIT Supplier (ACB DS)
			UIT Supplier (ACB KA)
			UIT Supplier (ACB KA)
			UIT Access Control Broker (KA)
			UIT Transitional CoS (DS)
	2	Test Certificates	GFI Root
			GFI Recovery
			GFI Supplier (Supplier DS)
			GFI Supplier (Supplier KA)
			GFI Supplier (Supplier KA Prepayment Top Up)
			GFI Access Control Broker (KA)
			GFI Transitional CoS (DS)
PPMID	10	Production Certificates	UIT Root
			UIT Recovery
			UIT Access Control Broker (DS)
			UIT Access Control Broker (KA)
IHD	10	Production Certificates	-